

Installation

Client site:	52°34'23.1"N 2°11'09.0"W
Conducted on:	2025-02-17
Number of Cameras:	8
System:	IP System
Equipment used:	8 x DS2CD2687G2HT-LIZS 1 x DS-2CD2387G2H-LISU/SL Hikvision DS-7716NXI-I4/S 16-Channel 8-TB-HDD Ruijie RG-ES118S-LP 16-port Switch 1 x Data cab
Number of cameras:	8
Description of works:	All cameras have been cabled and all cameras have been fitted to the poles.


Work Image 1



Work Image 2



Work Image 3



Work Image 4

Work Image 5

Work Image 6





Equipment Locations

Camera Location Image 1

Camera Location Image 2


Camera Location Image 3



Camera Location Image 4

Camera Location Image 5

Camera Location Image 6



Switch and power location:

Switch and power location image



Recorder location:

Recorder location image



Additional Information:

Audit

CCTV system is installed and programmed per proposal and is operational.: No



Camera angles are adjusted and approved by the customer:

No



Customer is satisfied with cleanliness:

Yes

Customer has been trained with camera system including live view, motion detection, and recording retrieval. The customer is satisfied with CCTV customer orientation training:

No

Customer Name:

Paul

Customer Signature:
