


Installation

Client site:	Bob Francis Queensferry
Conducted on:	2024-12-13
Number of Cameras:	0
System:	IP System
Equipment used:	Cable and crimps
Number of cameras:	0
Description of works:	Ran a new cable and split the 4 cams so they ran off 2 power supply rather than one

Work Image 1

Work Image 2

Work Image 3



Work Image 4

Work Image 5

Work Image 6



Equipment Locations

Camera Location Image 1

Camera Location Image 2


Camera Location Image 3



Camera Location Image 4

Camera Location Image 5

Camera Location Image 6



Switch and power location:

Switch and power location image



Recorder location:

Recorder location image



Additional Information:

Audit

CCTV system is installed and programmed per proposal and is operational.: Yes



Camera angles are adjusted and approved by the customer:

Yes



Customer is satisfied with cleanliness:

Yes

Customer has been trained with camera system including live view, motion detection, and recording retrieval. The customer is satisfied with CCTV customer orientation training:

Yes

Customer Name:

Customer Signature:
