


## Installation

Client site:	Laprino
Conducted on:	2024-12-12
Number of Cameras:	1
System:	IP System
Equipment used:	Cable RJ45 cable ties
Number of cameras:	1
Description of works:	Ran a cable from camera in void to system

**Work Image 1**

**Work Image 2**


**Work Image 3**



**Work Image 4**

**Work Image 5**

**Work Image 6**




**Equipment Locations**

**Camera Location Image 1**

**Camera Location Image 2**


**Camera Location Image 3**



**Camera Location Image 4**

**Camera Location Image 5**

**Camera Location Image 6**



Switch and power location:

**Switch and power location image**



Recorder location:

**Recorder location image**



Additional Information:

**Audit**

CCTV system is installed and programmed per proposal and is operational.: Yes



Camera angles are adjusted and approved by the customer:

Yes



Customer is satisfied with cleanliness:

Yes

Customer has been trained with camera system including live view, motion detection, and recording retrieval. The customer is satisfied with CCTV customer orientation training:

Yes

Customer Name:

Dewi

Customer Signature:

---