



## Installation

Client site:	Anthony Oldham
Conducted on:	2025-06-26
Number of Cameras:	3
System:	IP System
Equipment used:	2 pano view and one colour view
Number of cameras:	3
Description of works:	


**Work Image 1**




**Work Image 2**



**Work Image 3**



**Work Image 4**



**Work Image 5**

**Work Image 6**

## Equipment Locations

**Camera Location Image 1**

**Camera Location Image 2**

**Camera Location Image 3**



**Camera Location Image 4**

**Camera Location Image 5**

**Camera Location Image 6**



Switch and power location:

**Switch and power location image**



Recorder location:

**Recorder location image**



Additional Information:

**Audit**

CCTV system is installed and programmed per proposal and is operational.: Yes



Camera angles are adjusted and approved by the customer: Yes



Customer is satisfied with cleanliness: Yes

Customer has been trained with camera system including live view, motion detection, and recording retrieval. The customer is satisfied with CCTV customer orientation training: Yes

Customer Name: Anthony



Customer Signature:

)

