


## Installation

Client site:	Quinton Hazell Enterprise Parc, Glan-Y-Wern Rd
Conducted on:	2025-01-19
Number of Cameras:	6
System:	HD System
Equipment used:	6x hd cams
Number of cameras:	6
Description of works:	installed 6 new cameras with new system

**Work Image 1**

**Work Image 2**


**Work Image 3**



**Work Image 4**

**Work Image 5**

**Work Image 6**




**Equipment Locations**

**Camera Location Image 1**

**Camera Location Image 2**


**Camera Location Image 3**



**Camera Location Image 4**

**Camera Location Image 5**

**Camera Location Image 6**



Switch and power location:

**Switch and power location image**



Recorder location:

**Recorder location image**



Additional Information:

**Audit**

CCTV system is installed and programmed per proposal and is operational.: Yes



Camera angles are adjusted and approved by the customer:

Yes



Customer is satisfied with cleanliness:

Yes

Customer has been trained with camera system including live view, motion detection, and recording retrieval. The customer is satisfied with CCTV customer orientation training:

Yes

Customer Name:

Quinton Hazell

Customer Signature:

---