


Installation

Client site:	A1 storage Wrexham
Conducted on:	2026-02-09
Number of Cameras:	5
System:	IP System
Equipment used:	
Number of cameras:	5
Description of works:	Installed 5 x ip cameras in planned locations Also installed anpr and horn speaker System is by the entrance in the container connected to a sim router All equipment fitted and tested Work carried out at a high standard Using 25mm Copex for protection

Work Image 1

Work Image 2

Work Image 3



Work Image 4

Work Image 5

Work Image 6




Equipment Locations

Camera Location Image 1

Camera Location Image 2


Camera Location Image 3



Camera Location Image 4

Camera Location Image 5

Camera Location Image 6



Switch and power location:

Switch and power location image



Recorder location:

Recorder location image



Additional Information:

Audit

CCTV system is installed and programmed per proposal and is operational.: Yes



Camera angles are adjusted and approved by the customer:

Yes



Customer is satisfied with cleanliness:

Yes

Customer has been trained with camera system including live view, motion detection, and recording retrieval. The customer is satisfied with CCTV customer orientation training:

Yes

Customer Name:

Customer Signature:
