

## **Job Sheet**

Client site:	Johnson's Wrexham
Site contact:	Anton
Date of job:	2025-01-02
Days on site:	1
Engineer on site:	Matt and Matty
Type of job:	installation
Number of cameras:	2
Camera locations:	1. Opposite smoking shelter by reception. 2. Bottom yard on the right of the building above the serrated fence next to the ramp.

## Camera Location Image 1


Camera Location Image 2

**Camera Location Image 3** 



**Camera Location Image 4** 

**Camera Location Image 5** 



Recorder location:

Engineering and top office

## **Recorder Location Image**



Installation instructions:

Additional Information:

Swap over the two cameras for the new colorvu bullets and swap the head drive in engineering system.

Pick up kit from connectec and return the old kit to the office to be refunded by supplier.