


Job Sheet

Client site:	Blue water
Site contact:	Lisa
Date of job:	2025-01-07
Days on site:	1
Engineer on site:	Matt / Matty
Type of job:	Service
Number of cameras:	NA
Camera locations:	NA

Camera Location Image 1

Camera Location Image 2

Camera Location Image 3



Camera Location Image 4

Camera Location Image 5

Camera Location Image 6



Recorder location:

NA

Recorder Location Image



Installation instructions:

There is a camera off after the storm they had a power cut.

Additional Information:

Put the reason why it was off on the sheet and time on site.
